Winclon User's Manual BINCONET MARINE SOLUTIONS Co., Ltd.

Quality is the best business plan for our best customer

2022. 04. 13. Quality Management Department Ryun Ha Lee



How to use a winclon using F11



Quality is the best business plan for our best customer

- 1. Power up your PC.
- 2. At boot time, enter F11 on the appropriate screen to enter the RECOVERY ZONE.





Quality is the best business plan for our best customer

3. Enter the RECOVERY ZONE and click the Recovery button in the center.



Quality is the best business plan for our best customer

4. Click YES in the dialog box below to proceed with the recovery.

WinClon	23	
WinClon 6 Premium	Advanced	
<complex-block> I current data on the Windows drive will be deleted upon starting Restore to recent st I current data on the Windows drive will be deleted upon starting o you want to continue? I want to continue? I our an restore to the state you want. Shortcut I our an back up to a location you want. Shortcut</complex-block>	recent state [F10]	
CLONIX)

Quality is the best business plan for our best customer

5. After the repair is completed, use the upper right X button to exit the WINCLON

		the second s	2
WinClon 6 Premi	um		
Restoration is in progress. Please, Image file: D:\WinClonBackup\Use	do not turn off your computer while restoration er.wcl	is in progress.	
40/23006MB	40MB/S	00:00:01/0	0:00:00
40/23006MB Restoration in progress	40MB/S	00:00:01/0	0:00:00

How to use a winclon using BOOTING USB

Quality is the best business plan for our best customer

- 1. After connecting the BOOTING USB, apply power to the PC.
- 2. Enter BIOS MODE by typing DELETE on the appropriate screen at boot time.

Quality is the best business plan for our best customer

- 3. Enter BIOS MODE and go to BOOT TAP
- 4. Change Boot Option #1 to the indicated Generic Flash Disk (Booting USB).

Main	Advanced	Chipset	Security	Boot Save & Exit	
Boot C Setup Quiet Fast B	Configurati Prompt Tim Boot oot	on eout		1 [Disabled] [Disable]	Sets the
Boot 0	ption Prior ption #1	rities		[Windows Boot Manager	
Boot Of	otion #2	_		(P2: TS120GMTSB20S)] [UEFI: Generic Flash Disk 8.07, Partition 1]	
			Windows Bo UEFI: Gene Disabled	Boot Option #1 Pot Manager (P2: Toissource Pric Flash Disk 8.07. Part)	tion 1
					+/-: Char F1: Gener F8: Prev F9: Optin F10: Save ESC: Exit

Quality is the best business plan for our best customer

5. Change the BOOT order and go to SAVE & EXIT TAP.

6. Click SAVE CHANGES AND RESET to proceed.

Main	Advanced	Chipset	Security	Boot S	ave & Exit		1
Save O Save C Discard	otions hanges and d Changes	Reset and Reset					Reset the sys the changes.
Default Restore	t Options e Defaults						
Boot Ov Windows UEFI: C	verride : Boot Man Generic Fla	ager (P2: ash Disk (TS120GMTS 3.07, Sav	SB2OS) ————————————————————————————————————	ive & reset - guration and	reset?	+: Select S
				Yes	N	0	↓: Select nter: Selec /-: Change
							F1: General F8: Previou F9: Optimiz F10: Save & ESC: Exit

Bincone+

Quality is the best business plan for our best customer

7. After reset, enter the RECOVERY zone automatically and click the displayed Shortcut to enter

Quality is the best business plan for our best customer

8. Click the displayed WIZARD to enter.

WinClon 6 Premium

Restore Windows configuration to the previously backed-up state.

Select an image file to restore.

Date	Time	Drive	Size	Туре	Description	
2022.04.10	19:36:45	Recovery Zone	13.22GB	Master	Factory Image	

Quality is the best business plan for our best customer

- 9. Enter WIZARD and click in the upper right corner.
- 10. Select BOOTMEDIA \rightarrow WINCLONBACKUP \rightarrow WCL FILE and click OK.
- 11. Select the image as above and click NEXT.

Quality is the best business plan for our best customer

12. Change the boxed item to Restore entire disk and click Next.

WinClon Wizard	
Structure of the selected image	
C:\WinClonBackup\20220410-224354_Default strin	ng_Windo
- I-:] (NTFS)	24.7 / 81.4 GB
[-:] (NTFS)	13.3 / 28.8 GB
[-:] (FAT32)	0.5 / 1.0 GB
Choose the range for the restore	
Restore entire disk	
In case of restoring entire disk by using partition backup image, all partitions except formatted.	pt for backed up partition are
CLONIX	< Prev Next >

Quality is the best business plan for our best customer

13. Select the items marked in the box and click Next.

WinClon Wizard

Adjust the last partition to fit the disk.		
ACLONIX	< Prev	Next >

Quality is the best business plan for our best customer

14. Click Restore to proceed with the recovery.

WinClon Wizard

Backup image file

20220410-224354_Default string_Windows10.wcl

Collection of defragmenter when restoring Enable

Quality is the best business plan for our best customer

15. After performing the recovery as shown below, use the upper right X button to exit the WINCLON.

WinClon Wizard

